

IMDM OUTER

Access Gate ETF 74M 0000 YRDs Eastleigh South Junction
OUT OF USE UNTIL FURTHER NOTICE

Risk: Land Contamination with potential asbestos


Incident

On the 15th of May at 14:40 2 members of Eastleigh P/Way staff were departing a work site through Eastleigh Works after working on the **ETF** when they were approached and informed that the land that they had just driven over was contaminated with asbestos.

This incident is currently under investigation.

We are currently working hard to establish:

- If and what contamination is present
- What the risks are to others working in and around the area of land
- What control measures have been put in place.
- Why the area used to gain access to the track was not fenced off and clearly sign posted



ACCESS TO EASTLEIGH WORKS

Please ensure anyone entering Eastleigh Works signs in at gate 2 gatehouse where important information may be available.

With immediate the track access gate on the ETF at:

74M 0000Yrds, Eastleigh South Junction on the UP Side is closed until further notice