


IP Southern Safety Flash 16-06 dated 28 January 2016

**Incorrect labelling of Safety 365 de-icer**



It has been found that some of the 'Safety 365 de-Icer' products that were being used in Network Rail Delivery Units were incorrectly labelled.

After removing the de-Icer label, it was found that the original label underneath is actually for a brake cleaner. In some cases the product contained inside has been confirmed as brake cleaner which is corrosive to vehicle paint, highly flammable and can be an irritant to skin.

**Action:** All Safety 365 De-Icer products should be taken out of circulation and replaced with an alternative de-icing product. A Close Call should also be raised.