

Wessex Safety Learning Event

On Sunday 7 January an incident occurred when an earthing strap was accidentally dropped on a live conductor rail while a possession isolation was being taken. This caused a flash and resulted in the individual involved being taken to hospital to check their sight.



For further information contact: Steve Edwards Inner WHSEA (steven.edwards@networkrail.co.uk)

Discussion points:

Everyone should discuss these points with their teams – whether in the office or on site. Please send any feedback to Steve.

- How can you prevent tools and/or equipment coming into contact with the 3rd rail?
- How can you protect your eyes and what can/do you do following an eye injury?